

Boiler Draft System (BDS) Primary Air Fan (PA Fan) > Pillow Block Bearing

FAULT TYPE:


- Lubrication Condition Based Monitoring (CBM)

INDICATION:

- High-frequency noise consistent with a lubrication issue was identified as a recurring problem, but resolved when grease was applied
- Warning thresholds established to send automated notification when vibration levels occurred that were consistent with previous known instances of need for lubrication

ACTION TAKEN:

- Condition Based Monitoring (CBM) Lubrication program established to allow operation of equipment until next scheduled outage



Automated Email Alert

This email was generated as a result of you requesting to be notified of the following event:

On 3/21/2023 10:27:26 AM Eastern Standard Time

Niagara Falls, NY > Waste-to-Energy > PA Fans > #3 PA Fan > #3 PA Fan > Fan Outboard (large) > Radial (Y) > Peak Acceleration is in Warning

[Click here to acknowledge this event.](#)

This message is automatically generated. If you think it was sent incorrectly please contact your administrator.

KCF Technologies, Inc. 336 South Fraser Street
State College, PA 16801
814.867.4097

