


Boiler Draft System (BDS) Primary Air Fan (PA Fan) > Fan

FAULT TYPE:

- Fan Imbalance (Buildup)


INDICATION:

- Overall Vibration levels gradually spiked up into Warning & eventually Alarm thresholds.
- Vibration pattern showing elevated 1x & harmonics present, dominantly in the Axial direction of the fan.



ACTION TAKEN:

- Fan cleaned during next available outage.



Imbalance Vibration Pattern

"Healthy" Vibration Pattern Post Cleaning

